



Service Pricing for Öhlins MTB Products

Öhlins DTC, Version 1.1, valid from 29.05.2018

Explanations

At Öhlins DTC close to the Nürburgring, suspension is serviced to the manufacturer's desired quality level.

To maintain the product warranty, suspensions service shall only be performed by an authorized Öhlins Service Center for MTB products, using solely genuine service parts and spares as well as oil and grease recommended by the manufacturer.

The service charge includes all spare parts necessary as well as the labor time. At a regular service the product will be disassembled, all parts and components are checked for wear and all relevant seals will be replaced. After this, the product will be assembled and filled with fresh oil through a vacuum filling machine.

Not included in the service charge are all damaged or worn parts apart from the standard service procedure. Additional cost may occur for replacing these.

Before we start working, we will send a cost indication to sign off. We reserve the right to invoice a charge of € 55,00 if no service is carried out after price indication.

Products sent for service have to be cleaned, otherwise € 35,00 will be charged for cleaning them.

Products will be sent back free of charge after service.

All prices are in EURO.

For further information, please visit www.ohlins.eu.

Your workshop team at Öhlins DTC

Forks

RXF 34 Air / RXF 36 Air 27,5 & 29	Price excl. VAT	Price incl. 19% VAT
50h service (Lower Leg Service)	€ 54,62	€ 65,00
100h service (Full-Service)	€ 180,67	€ 215,00
'Air' stroke change var. 1 (see chart)	€ 138,66	€ 165,00
'Cartridge' stroke change var. 2 (see chart)	€ 390,76	€ 465,00
Setting change	€ 79,83	€ 95,00
Converting cartridge from STX (OEM) to TTX (aftermarket)	€ 331,93	€ 395,00

Stroke change RXF 34 Air / RXF 36 Air

Stroke in mm	from 120	from 140	from 150	from 160	from 170
to 120	-	var. 1	var. 2	var. 2	var. 2
to 140	var. 1	-	var. 2	var. 2	var. 2
to 150	var. 2	var. 2	-	var. 1	var. 1
to 160	var. 2	var. 2	var. 1	-	var. 1
to 170	var. 2	var. 2	var. 1	var. 1	-

RXF 36 Coil 27,5 & 29	Price excl. VAT	Price incl. 19% VAT
50h service (Lower Leg Service)	€ 54,62	€ 65,00
100h service (Full-Service)	€ 142,86	€ 170,00
Stroke change	€ 37,82	€ 45,00
Converting fork from coil spring to air spring	€ 331,93	€ 395,00
Setting change	€ 79,83	€ 95,00

Shock Absorbers

STX 22 Air / Custom	Price excl. VAT	Price incl. 19% VAT
Air spring service	€ 54,62	€ 65,00
Full service (air spring and damper)	€ 180,67	€ 215,00
Setting change	€ 79,83	€ 95,00
Compression valve change	€ 147,06	€ 175,00

TTX 22 M	Price excl. VAT	Price incl. 19% VAT
Full Service	€ 168,07	€ 200,00
Setting change	€ 79,83	€ 95,00
Compression valve change	€ 79,83	€ 95,00

Additional Services

Description	Price excl. VAT	Price incl. 19% VAT
Product cleaning	€ 29,41	€ 35,00
Price indication without servicing	€ 46,22	€ 55,00