



## Service Pricing for Öhlins MTB Products

Öhlins Europe, Version 1.3, valid from 15.01.2021

### Explanations

At Öhlins Europe close to the Nürburgring, suspension is serviced to the manufacturer's desired quality level.

To maintain the product warranty, suspensions service shall only be performed by an authorized Öhlins Service Center for MTB products, using solely genuine service parts and spares as well as oil and grease recommended by the manufacturer.

The service charge includes all spare parts necessary as well as the labor time. At a regular service the product will be disassembled, all parts and components are checked for wear and all relevant seals will be replaced. After this, the product will be assembled and filled with fresh oil through a vacuum filling machine.

Not included in the service charge are all damaged or worn parts apart from the standard service procedure. Additional cost may occur for replacing these.

Before we start working, we will send a cost indication to sign off. We reserve the right to invoice a charge of € 55,00 incl. 19 % VAT if no service is carried out after price indication.

Products sent for service have to be cleaned, otherwise € 35,00 incl. 19 % VAT will be charged for cleaning them.

Products will be sent back free of charge after service.

All prices are in EURO.

For further information, please visit [www.ohlins.eu](http://www.ohlins.eu).

Your workshop team at Öhlins Europe

## Forks

<b>RXF Air/DH 38 Air</b>	<b>Price excl. VAT</b>	<b>Price incl. 19% VAT</b>
50h service (lower leg Service)	€ 67,90	€ 80,00
100h service (lower leg/air spring)	€ 189,50	€ 225,00
200h service (lower leg/air spring/damper service)	€ 219,95	€ 260,00
Fork full rebuild (air spring/damper/bushes)	€ 339,23	€ 400,00
Stroke change on request	-	-
Setting change	€ 79,83	€ 95,00
Converting cartridge from STX/TTX22m to TTX 18	€ 332,00	€ 395,00

<b>RXF Coil</b>	<b>Price excl. VAT</b>	<b>Price incl. 19% VAT</b>
50h service (Lower Leg Service)	€ 67,90	€ 80,00
100h service (lower leg/spring service)	€ 147,01	€ 175,00
200h service (lower leg/spring service/damper service)	€ 197,73	€ 235,00
Fork full service (rebuild spring/damper service/ bushes)	€ 317,01	€ 380,00
Stroke change on request	-	-
Setting change	€ 79,83	€ 95,00

## Shock Absorbers

<b>STX 22 Air</b>	<b>Price excl. VAT</b>	<b>Price incl. 19% VAT</b>
Air spring service	€ 79,83	€ 95,00
Full service (air spring and damper)	€ 186,11	€ 220,00
Setting change	€ 79,83	€ 95,00
Compression valve change	€ 147,05	€ 175,00

<b>TTX Air</b>	<b>Price excl. VAT</b>	<b>Price incl. 19% VAT</b>
Air spring service/oil change	€ 131,83	€ 155,00
200h service (air spring and damper)	€ 178,83	€ 210,00
Setting change	€ 79,83	€ 95,00

<b>TTX 22 M</b>	<b>Price excl. VAT</b>	<b>Price incl. 19% VAT</b>
100h service	€ 112,61	€ 135,00
Full rebuild service	€ 194,01	€ 230,00
Setting change	€ 79,83	€ 95,00
Compression valve change	€ 79,83	€ 95,00

## Additional Services



Description	Price excl. VAT	Price incl. 19% VAT
Product cleaning	€ 29,41	€ 35,00
Price indication without servicing	€ 46,22	€ 55,00