



# Service and Spare Parts Service kit chassis RXF 34

Chassis service kit for Öhlins RXF 34 forks.

Content of delivery:

2x bump rubbers

2x foam rings

2x wiper seals

1x O-ring (as SAG indicator)

Part number

18850-01

Fits for Mountain bikes

[Universal MTB Air Fork \( - \)](#)

## Price and availability

**25,29 €**

25,29 € plus % VAT

**in stock**

(3 - 5 business days)



## Performance Suspension Guide

Not sure what you need or how to set up your bike? The Öhlins Performance Suspension Guide will help you to find the right product and

base set up for you bike.

[Open Performance Suspension Guide](#)

The picture shown can deviate from the product delivered.



## Öhlins Europe

Gottlieb-Daimler-Straße 25  
53520 Meuspath  
Germany

Phone: +49 (0) 2691 -  
937780  
Fax: +49 (0) 2691 - 9377890  
E-Mail: [info.oeu@driv.com](mailto:info.oeu@driv.com)

## Office Hours

Monday to Friday  
08:00 AM to 12:30 PM  
01:30 PM to 05:00 PM

