



Service and Spare Parts Service kit chassis SKF RXF 38

Chassis service kit for Öhlins DH38 forks.

Content of delivery:

2x bump rubbers

2x foam rings

2x wiper seals

1x O-ring (as SAG indicator)

Part number

19237-01

Fits for Mountain bikes

[Universal MTB DH38 \(- \)](#)

Price and availability

44,94 €

44,94 € plus % VAT

Not in stock

We send you an email as soon as the product is in stock.



Performance Suspension Guide

Not sure what you need or how to set up your bike? The Öhlins Performance Suspension Guide will help you to find the right product and base set up for you bike.

[Open Performance Suspension Guide](#)

The picture shown can deviate from the product delivered.



Öhlins Europe

Gottlieb-Daimler-Straße 25
53520 Meuspath
Germany

Phone: +49 (0) 2691 -
937780
Fax: +49 (0) 2691 - 9377890
E-Mail: info.oeu@driv.com

Office Hours

Monday to Friday
08:00 AM to 12:30 PM
01:30 PM to 05:00 PM

