

IMPORTANT SAFETY RECALL NOTICE



ÖHLINS STEERING DAMPER BRACKETS - Produced between September 2008 and October 2013

Öhlins DTC regrets to inform there is a manufacturing defect that relates to motorcycle safety and exists in the brackets for Öhlins aftermarket steering dampers manufactured between September 2008 and October 2013.

The aluminum alloy is sensitive to stress corrosion cracking and there is also a risk the bracket will fail when steering is used to maneuver the bike in a small radius or with a maximum steering angle used in one direction.

If you have an Öhlins steering damper with the below mentioned part and batch no. for these bikes, please do not continue to use the bike before removing the steering damper and the bracket.

Öhlins has decided to recall all steering damper brackets and replace these with new brackets. For further action we kindly ask you to contact Öhlins DTC at info.odtc@ohlins.se. Please provide us with the part no. of the steering damper and the batch number and point of purchase. See the drawing beneath where to find the numbers on your product.

We apologize for any inconvenience this safety recall may cause and wish to thank you for your cooperation.

ÖHLINS DTC
Gottlieb-Daimler-Straße 25
D-53520 Meuspath
Deutschland
info.odtc@ohlins.se
www.ohlins.eu



Part and batch numbers for steering dampers with affected bracket

Part no.	Batchnumber	Part no. Bracket
SD 000	125476, 126040, 127647, 127340, 127 882, 127960, 128149, 131055 bis 135231	02205-11
SD 001	125205, 125351, 126041, 125477, 127339, 128150, 131405 bis 135104	02205-11
SD 002	302306, 125203, 125673, 125475, 126039, 127165, 131801 bis 134827	02205-11
SD 003	302305, 125202, 125474, 126038, 127334, 128067, 131406 bis 133946	02205-11
SD 004	302304, 125672, 125848, 126444, 127658, 128122, 131682 bis 134828	02205-11
SD 005	125473, 125923, 126141, 132714 bis 134956	02205-11
SD 020	All	02245-13
SD 027	302426, 126278, 126348, 127798, 127930, 128161, 131407 bis 135493	02205-11
SD 031	All	02240-12
SD 033	128351, 128352, 128650, 128738, 128794, 129238, 129647, 129670, 129712, 129946, 130555, 130582, 130789, 131127, 131562, 131766, 132234, 132560, 303667	
SD 037	131684, 303936	
SD 038	131657, 131894, 304004	
SD 041	All	02240-12
SD 120	125265, 125446, 125541, 125907	02240-02
SD 124	126899	02205-01
SD 137	126140, 133439	02205-01
SD 154	126863, 131563, 132190, 133010, 132844, 133816	02205-01
SD 170	126001	02205-01
SD 178	132933	02240-02
SD 180	125812	02205-01
SD 182	125811, 126138	02240-02
SD 183	133192	02245-03
SD 197	126900, 127282, 131685, 133440, 134067	02205-01
SD 215	131680	02205-11